

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Effland (55 unsigned docs, Responsible for 214 docs)			
Add New Hole Locations To RAL Drawing Kg0772-635b http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100364/			156
Waiver, Band 6 Cartridge SN 002: Power Density Slope http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105406	Modification Required (Draft)	Effland	657
Band 6 Cartridge 003 PAI Review Meeting Minutes http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105160	Modification Required (Draft)	Effland	642
Band 6 Cartridge 008 PAI Review Meeting Agenda http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104809	Modification Required (Draft)	Effland	598
Band 6 Template for Configured Items Data List http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105107	Modification Required (Draft)	Effland	638
Request for waiver on RF mismatch requirement of Band 6 windows FEND-40.03.01.04-06080-00	Modification Required (Draft)	Saini	511
Response to Band 6 Cartridge CDR Action Items http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104306	Modification Required (Draft)	Effland	567
Acceptance Report for Front-End Assembly SN-01 http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104861	Modification Required (Draft)	Saini	616
Optics Design Report, Appendix 6 http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103011	Modification Required (Draft)	Morris	299
Cartridge Bias Module Design Analysis Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102134/	Modification Required (Draft)	Saini	392
Waiver, Band 6 Cartridge SN 002: Noise Temperature 125% Limit http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105402	Modification Required (Draft)	Effland	654
Electromagnetic Properties Of The ALMA Antenna Front-end Analysis (optics) http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104132	Modification Required (Draft)	Haupt (ESO)	402
Waiver, Band 6 Cartridge SN 002: Signal Path Phase Stability http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105404	Modification Required (Draft)	Effland	656
Optics Design Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101887	Modification Required (Draft)	Haupt (ESO)	173
Waiver, Band 6 Cartridge 002: Total IF Output Power http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105407	Modification Required (Draft)	Effland	658
Bugs In This Software	Modification Required (Draft)	Effland	407
Band 6 Dummy OMT E-Plane Assy http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104724	Modification Required (Draft)	Morris	584

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Effland (55 unsigned docs, Responsible for 214 docs)			
Band 6 First LO Driver Assembly WCA6-10 Shipping Inspection Checklist http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104402/	Modification Required (Draft)	Saini	581
Revision of the Band 6 Cartridge Technical Specifications http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100574	Modification Required (Draft)	Effland	556
Band 6 Cartridge Technical Specification, Rev B http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/showFile/100622/d20070926171027/No/FEND-40.02.06.00.001-B01-SPE.pdf	Modification Required (Draft)	Effland	560
ALMA First Local Oscillator Driver Experimental Procedures for Acceptance Tests http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/101756/	Modification Required (Draft)	Saini	580
First Local Oscillator Driver for Band 6 Acceptance Procedures http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/showFolder/100472/	Modification Required (Draft)	Saini	583
Waiver, Band 6 Cartridge SN 002: Cross-Pol Isolation http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105403	Modification Required (Draft)	Effland	655
Band 6 Cartridge Test Procedure: IF Output Return Loss	Not Started	Effland	565
Band 6 OMT Statement of Work http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104152	Not Started	Effland	432
Band 3 OMT Statement of Work http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104151	Not Started	Effland	431
WCA Harness Plate http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/100902	Not Started	Morris	573
Waiver, Band 6 Cartridge SN 002: Amplitude Stability http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105492	Not Started	Effland	659
Band 6 Cartridge Reliability Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103696/def/def/3908784	Review (by Effland) Required	Effland	357
Band 6 Pattern Comparison, Summary Appendix For Optics Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102836	Review (Technical) Required	Saini	165
First Local Oscillator for Band 6 Acceptance Report (Serial No 10 / ACA deliverable article) http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104403	Review (Technical) Required	Saini	578
Band 6 Cartridge Specification http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100250	Signed - Needs modification	Effland	32
ALMA Front End RF & IF Path Budgets http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100739	Signed - Needs modification	Saini	664
ICD Between Front End Band 6 Cartridge And Front End IF Switch http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/101107	Signed - Needs modification	Saini	182

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Effland (55 unsigned docs, Responsible for 214 docs)			
Band 6 Cartridge Technical Design Document http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100994	Signed - Needs modification	Effland	67
ICD Between Band 6 Cartridge And Dewar http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100424	Signed - Needs modification	Effland	174
Management Plan For Band 6 Cartridge http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103236	Signed - Needs modification	Effland	278
Front End Product Tree http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100976	Signed - Needs modification	Rudolf (ESO)	316
First Local Oscillator Driver for Band 6 Acceptance Test Plan http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100297	Signing in Progress	Saini	579
Band 6 Cartridge 001: PAI Review Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/102615	Signing in Progress	Saini	251
First LO Assembly for Band 6 Configured Items Data List WCA6-10 http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104401/	Signing in Progress	Saini	582
Band 6 Cartridge 001: Acceptance Discrepancy Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/102571	Signing in Progress	Saini	250
ALMA Front End Cartridge Bias Module Technical Specifications http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101616/	Signing in Progress	Saini	390
Band-6 Coolable Frequency Tripler - Mechanical Details http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100426	Signing in Progress	Saini	535
Waiver, Band 6 Cartridge SN 003: Feedhorn and Adapter Corrosion http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105168	Signing in Progress	Saini	643
ICD Between WCA Connector Plate And Front End WCA Harness Plate http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100344	Signing in Progress	Saini	185
Band 6 Cartridge SN 004 PAS Test Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/105319	Signing in Progress	Saini	650
ICD Between Band 6 Cartridge And Band 6 1st LO http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/docProfile/100295	Signing in Progress	Saini	183
Waiver, Band 6 Cartridge SN 003: Signal Path Phase Stability http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105088	Signing in Progress	Saini	630
Waiver, Band 6 Cartridge SN 003: Power Density Slope http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105089	Signing in Progress	Saini	629
Waiver, Band 6 Cartridge SN 003: Noise Temperature 125% Limit http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105090	Signing in Progress	Saini	628

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Effland (55 unsigned docs, Responsible for 214 docs)			
Waiver, Band 6 Cartridge SN 003: Cross-Polarization Isolation http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105079	Signing in Progress	Saini	627
Band 6 Dummy OMT E-Plane Top Block http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104725	Signing in Progress	Morris	585
Band 6 Cartridge 007 PAI Review Meeting Minutes http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104911	Signing in Progress	Rudolf (ESO)	621
Band 6 Dummy OMT E-Plane Bottom Block http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104726	Signing in Progress	Morris	586
Responsible: Groves (3 unsigned docs, Responsible for 15 docs)			
Source Plates For LO And Sideband Sources	Modification Required (Draft)	Groves	377
Band 6 Cartridge General Bill Of Materials http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104135	Review (by Effland) Required	Effland	529
Band 6 Mixer Test System LO and SB Source System Manual http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/105186	Signed - Needs modification	Groves	644
Responsible: Horner (12 unsigned docs, Responsible for 94 docs)			
Band 6 Cartridge 4K Heatsink (Koller) PCB http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104626	Modification Required (Draft)	Schmitt	493
Band 6 Cartridge Assembly Procedures http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/100967	Signed - Needs modification	Horner	85
Band 6 Cartridge 4K Plate http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100658	Signing in Progress	Tomkins (RAL)	1
Band 6 Cartridge Test Procedure: Vibration, Shock, And Natural Frequency Testing http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101857	Signing in Progress	Saini	81
ALMA Band 6 G10 Support Tube Orientation http://edm.alma.cl/forums/alma/dispatch.cgi/f.frontendipt/showFile/100362/d20051021092409/No/FEND-40%2002%2006%2008-001-A-DWG.pdf	Signing in Progress	Morris	297
Cartridge Bias Module Connector(s) Mechanical Details http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101400	Signing in Progress	Saini	496
Band 6 Cartridge 110K Plate http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100657	Signing in Progress	Tomkins (RAL)	60
Band 6 Cartridge 300K Plate http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100659	Signing in Progress	Tomkins (RAL)	62

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Horner (12 unsigned docs, Responsible for 94 docs)			
Carter Mirror 2 http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104527	Signing in Progress	Morris	20
Carter Mirror 1 http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104526	Signing in Progress	Morris	19
Band 6 Cartridge Assembly Drawing http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101121	Signing in Progress	Morris	16
Band 6 Cartridge 15K Plate http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100656	Signing in Progress	Tomkins (RAL)	59
Responsible: Kerr (1 unsigned docs, Responsible for 11 docs)			
Mixer-Preamp Requirements	Not Started	Groves	533
Responsible: Koller (25 unsigned docs, Responsible for 51 docs)			
Band 6 OMT SN007 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103890	Checking Required	Effland	466
Band 6 OMT SN004 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103888	Modification Required (Draft)	Koller	463
Band 6 OMT SN002 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103886	Modification Required (Draft)	Koller	458
Band 6 OMT SN003 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103887	Modification Required (Draft)	Koller	460
Band 6 OMT SN006 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103889	Modification Required (Draft)	Koller	464
Band 6 OMT Drawing Set http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104121	Modification Required (Draft)	Morris	337
Band 6 OMT SN001 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103885	Modification Required (Draft)	Koller	459
Band 6 OMT SN009 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103899	Modification Required (Draft)	Koller	468
Band 6 OMT SN010 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103900	Modification Required (Draft)	Koller	475
Band 3 OMT SN 051 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102241	Review (by Effland) Required	Effland	333

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Koller (25 unsigned docs, Responsible for 51 docs)			
Band 3 OMT SN 073 Test Data Report http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103905	Review (by Effland) Required	Effland	473
Band 3 OMT Design Document http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103959	Review (by Effland) Required	Effland	477
Band 6 OMT Design Document http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103939	Signed - Needs modification	Koller	478
Band 6 OMT Block RFQ http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103799	Signing in Progress	Saini	444
Band 6 OMT Specifications http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103774	Signing in Progress	Saini	394
Band 6 OMT Test Procedures http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103801	Signing in Progress	Saini	447
Band 3 OMT Septum Coupon http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104126	Signing in Progress	Morris	521
Band 6 OMT Septum http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104123	Signing in Progress	Morris	522
Band 6 OMT Septum Coupon http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/104124	Signing in Progress	Morris	523
Band 3 OMT Test Procedures http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102031	Signing in Progress	Saini	336
Band 3 OMT Specifications http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102030	Signing in Progress	Saini	335
Band 3 OMT Septum http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/102047	Signing in Progress	Morris	520
Band 3 OMT Block Request For Quotes http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103901	Signing in Progress	Saini	384
Band 3 OMT Acceptance Test Plan http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103962	Signing in Progress	Saini	497
Band 6 OMT Acceptance Test Plan http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103963	Signing in Progress	Saini	498
Responsible: Lacasse (5 unsigned docs, Responsible for 14 docs)			
Band 6 Mixer-preamp And Cartridge Measurement System Software Specifications http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/100666	Checking Required	Lacasse	92

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Lacasse (5 unsigned docs, Responsible for 14 docs)			
Auto LO Software Requirements http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/100604	Modification Required (Draft)	Lacasse	84
Band 6 Cartridge Database Design Description http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103633	Modification Required (Draft)	Nagaraj	332
Cartridge Data Formats For Delivery To The Front End Integration Centers http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103345	Signing in Progress	Lacasse	342
Data Formats for Cartridge Operating Parameters http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101104	Signing in Progress	Lacasse	507
Responsible: Lambeth (6 unsigned docs, Responsible for 12 docs)			
Mixer-Preamp Construction Tracking Spreadsheet \\Cvfiler\cv-cdl-sis\Cartridge\Mixer-Preamp\Mixer-Preamp_Component_Inventory.xls	Modification Required (Draft)	Effland	294
Band 6 Mixer Coupling Probe Metal (2) http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103964	Modification Required (Draft)	Morris	499
Capacitors for Band 6 Mixer-Preamp Tuning Network http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104133	Modification Required (Draft)	Morris	527
Band 6 Mixer-Preamp Repair Manual http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/103795	Not Started	Lambeth	389
Bias Circuit Simulator \\Cvfiler.nrao.edu\cv-cdl-sis\Cartridge\BiasCkt\IntfConn.dwg	Review (by Effland) Required	Effland	157
Band 6 Mixer Assembly Procedures http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/100971	Signed - Needs modification	Lambeth	137
Responsible: M. Morgan (3 unsigned docs, Responsible for 15 docs)			
IF 4-12 Type III Amp, Wiring Harness Bracket http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104586	Modification Required (Draft)	Morris	135
Assembly Procedures For ALMA Band 6 4-12 GHz IF Amplifiers http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/102750	Signed - Needs modification	Lambeth	354
IF 4-12 Type III Amp, Bottom Lid http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/104585	Signed - Needs modification	Morris	134
Responsible: Schmitt (20 unsigned docs, Responsible for 49 docs)			

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Schmitt (20 unsigned docs, Responsible for 49 docs)			
Band 6 Cartridge Production Plans http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/showFolder/103976	Modification Required (Draft)	Effland	490
Band 6 Cartridge Test Procedure: Noise Performance and Gain http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101778	Modification Required (Draft)	Effland	205
Band 6 Cartridge 008 Configured Items Data List http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/103734	Modification Required (Draft)	Groves	590
Band 6 Cartridge 008 PAI Test Report \\cvfiler.nrao.edu\cv-cdl-sis\CartTstData\Cart6.008productionTSTdata\PAIreport\Cart6.008_PAItestReport.doc	Modification Required (Draft)	Effland	587
Band 6 Test Procedure: RF Beam Efficiency http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101846	Modification Required (Draft)	Effland	209
Test Diagram, Warm Pattern Measurement Amplitude Only	Not Started	Schmitt	295
Band 6 Cartridge 300K Plate Leak Test Procedures	Not Started	Horner	562
Band 6 Cartridge Transport Tube	Not Started	Morris	622
Band 6 Cartridge Shipping Container	Not Started	Morris	623
Band 6 Cartridge Test System (CTS) Manual http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/showFolder/100973	Signed - Needs modification	Schmitt	88
Band 6 Cartridge Test Procedure: IF Output Power http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101856	Signed - Needs modification	Saini	80
Band 6 Cartridge Assembly Procedure: Warm IF Amplifier Subassembly http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/103614	Signed - Needs modification	Lambeth	322
Band 6 Cartridge Test Procedure: Phase Drift Measurement http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101867	Signing in Progress	Saini	82
Band 6 Cartridge Test Procedure: Polarization Alignment http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101855	Signing in Progress	Saini	107
Band 6 Cartridge Test Procedure: Gain Saturation http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101821	Signing in Progress	Saini	77
Band 6 Cartridge Test Procedure: Stabilization Time Measurement http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/showFolder/103361	Signing in Progress	Saini	306
Band 6 Cartridge Test Procedure: Spurious Response http://edm.alma.cl/forums/alma/dispatch.cgi/jptfedocs/docProfile/101879	Signing in Progress	Effland	83

Band 6 Cartridge and B3/6 OMT Documentation Status: Unsigned Documents

<u>Title</u>	<u>Status</u>	<u>Waiting On</u>	<u>Rec. #</u>
Responsible: Schmitt (20 unsigned docs, Responsible for 49 docs)			
Band 6 Cartridge Test Procedure: Amplitude Stability http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101844	Signing in Progress	Saini	78
Band 6 Cartridge Test Procedure: RF Beam Pattern Measurement http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/showFolder/103631	Signing in Progress	Saini	331
Band 6 Cartridge Test Procedure: Sideband Ratio Measurement http://edm.alma.cl/forums/alma/dispatch.cgi/iptfedocs/docProfile/101802	Signing in Progress	Saini	76